


Offshore Readiness Review

Technical resilience, crew preparedness and confidence for a demanding cruising programme

PREPARED FOR	Demonstration Client
VESSEL	M/Y Ardent
BUILDER / MODEL	Marineridge 54 Explorer
PRIMARY PROGRAMME	UK to Caribbean via Canaries
REVIEW DATE	15 July 2026
READINESS RATING	Conditionally Ready

Absolute Marine
Commercial thinking for private cruising.

EXAMPLE CLIENT JOURNEY



CLEARLY FICTIONAL
PRACTICALLY REALISTIC

The vessel, builder, client and service history are invented.

EXAMPLE REPORT

Document control and publication notice

This completed Offshore Readiness Review demonstrates the scope, structure and style of an Absolute Marine client report. It is intended to help prospective clients understand the type of interpretation, prioritisation and engineering judgement provided by the service.

FICTIONAL EXAMPLE	The client, vessel, builder, surveyor, maintenance history, findings, costs and cruising plans in this report are entirely fictional. The document must not be used to make decisions about any real vessel or voyage.
-------------------	--

Document field	Entry
Client	Demonstration Client
Vessel	M/Y Ardent
Builder / model	Marineridge 54 Explorer (fictional)
Report date	15 July 2026
Report reference	AM-ORR-EX-01
Version	1.0
Prepared by	Absolute Marine

Report status

Version	Date	Description	Prepared / reviewed by
1.0	15 July 2026	Public fictional example	Absolute Marine

Publication use

This example may be published by Absolute Marine as an illustration of its services. It is not a survey, certificate of seaworthiness, voyage approval or representation that any real vessel possesses the characteristics described.

REPORT STRUCTURE

Contents

The report moves from the engagement basis and decision-level overview into the detailed technical assessment, practical recommendations and final engineering opinion.

Section	Title	Purpose
01	Scope and Methodology	Assessment basis, methodology and limitations
02	Executive Dashboard	Decision-level readiness overview
03	Offshore Readiness Summary	Status across all principal areas
04	Intended Cruising Programme	Operational demands and assessment baseline
05	Machinery Readiness	Propulsion, generation and supporting machinery
06	Fuel System Assessment	Storage, filtration and contamination resilience
07	Electrical Resilience	Charging, batteries, distribution and emergency power
08	Steering & Control Systems	Primary, backup and emergency steering
09	Safety & Emergency Preparedness	Equipment, procedures, medical and response capability
10	Crew & Operational Preparedness	Experience, planning, procedures and decision making
11	Communications & Navigation	Primary systems, backups and situational awareness
12	Spares Strategy	Repair capability, inventory and self-sufficiency
13	Detailed Readiness Assessment	Integrated risk and suitability judgement
14	Recommendations	Prioritised action plan
15	Conclusion	Final engineering opinion
16	Disclaimer	Scope, limitations and reliance

SECTION 01

Scope and Methodology

This review assesses the fictional vessel, its systems and the intended crew against a defined programme from the United Kingdom to the Caribbean. It focuses upon reliability, recoverability and the practical ability to manage foreseeable problems away from immediate support.

Purpose

The owner intends to depart the United Kingdom in September 2026, cruise to Portugal and the Canary Islands, and undertake an Atlantic passage to the eastern Caribbean during the established winter crossing period. The objective of this review is to identify what is already suitable, what remains vulnerable and which actions should be completed before departure.

Information reviewed

Information	Extent
Owner interview and systems walk-through	Two remote sessions totalling 3.5 hours
Maintenance and repair records	2019-2026 records plus recent invoices
Photographic systems record	214 current images and short machinery videos
Pre-purchase survey and repair evidence	Survey dated 10 June 2026 and completion photographs
Equipment manuals and inventory	Digital manuals, spare-parts list and safety certificates
Proposed voyage plan	UK, Biscay, Iberia, Canaries and Caribbean

Methodology

- Assess each critical area against the actual voyage rather than an abstract offshore standard.
- Consider reliability, redundancy, maintainability, crew familiarity and the consequence of foreseeable failure.
- Distinguish actions required before departure from improvements that may be completed during later maintenance.
- Use a four-level readiness rating: Ready, Conditionally Ready, Significant Preparation Required or Not Currently Ready.

Limitations

This fictional example assumes a document-led review supported by owner interviews and photographs. A real engagement may include a vessel visit where agreed. The service is not a condition survey, statutory inspection, sea trial, class assessment or guarantee of seaworthiness.

ASSESSMENT PHILOSOPHY	Offshore readiness is not established by equipment inventory alone. A system is only resilient when it is maintained, understood, accessible, supported by appropriate spares and accompanied by a practical method of recovery after failure.
-----------------------	--

SECTION 02

Executive Dashboard

The vessel has a credible offshore platform and several strong systems, but departure should remain conditional upon fuel, electrical, safety and spares actions being completed and demonstrated.

Vessel details

Item	Details
Vessel	M/Y Ardent
Type	Long-range semi-displacement motor yacht
Year / construction	2008 / GRP
Length overall	16.4 m
Propulsion	Twin 400 hp diesel engines; 2,900 hours approximately
Generator	13.5 kW diesel; 1,450 hours approximately
Fuel / water	4,200 litres / 1,000 litres
Typical crew	Experienced owner couple; two additional crew for Atlantic passage

Intended programme

Field	Programme
Primary route	South coast UK — Biscay — Portugal — Canaries — eastern Caribbean
Longest expected passage	Approximately 18–22 days Canaries to Caribbean
Operating period	September 2026 to April 2027
Support profile	Frequent support in Europe; limited immediate support during Atlantic passage
Environmental demands	Heavy-weather avoidance, prolonged machinery operation, tropical heat and long fuel intervals

Overall offshore readiness rating

☐ READY	☒ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--------------------------------	--	---	--

Key strengths

- ✓ Twin propulsion with good access and recent baseline servicing.
- ✓ Substantial fuel capacity and practical tank isolation arrangements.
- ✓ Hydraulic steering with independent emergency tiller and dual autopilot computers.
- ✓ Comprehensive primary navigation, radar, AIS and long-range communications.

Principal concerns

- ⚠ Primary fuel filtration lacks true underway changeover capability.
- ⚠ House-bank endurance and alternative charging performance have not been demonstrated under passage load.
- ⚠ Critical spares inventory is incomplete and poorly indexed.
- ⚠ Crew emergency drills and multi-day watchkeeping trial remain outstanding.

Immediate priorities

Priority	Action	Departure effect
1	Install serviceable fuel-filter changeover arrangements and verify tank cleanliness.	Departure condition
2	Complete house-bank endurance test and establish independent emergency charging.	Departure condition
3	Service dated safety equipment and complete practical emergency drills.	Departure condition
4	Build and stow a critical spares inventory with repair procedures.	Departure condition

EXECUTIVE CONCLUSION	M/Y Ardent is considered conditionally ready for the intended programme. The vessel's underlying machinery, steering and navigation arrangements provide a sound basis for offshore operation. The remaining deficiencies are manageable but material because they affect recovery from fuel contamination, prolonged electrical demand, emergency response and self-sufficiency. Departure should follow completion and practical demonstration of the Priority 1 actions.
-----------------------------	---

SECTION 03

Offshore Readiness Summary

The ratings show where the vessel is already credible and where the present programme relies upon work that has not yet been completed or demonstrated.

Area	Status	Comment
Cruising programme alignment	AMBER	The vessel is capable, but the Atlantic leg materially raises self-sufficiency requirements.
Machinery readiness	GREEN	Recent baseline servicing, twin propulsion and good access.
Fuel system	AMBER	Capacity is good; contamination recovery and filter changeover need improvement.
Electrical resilience	AMBER	Multiple sources exist, but endurance and emergency charging remain unproven.
Steering & control	GREEN	Hydraulic steering, dual autopilot computers and practical emergency tiller.
Safety & emergency preparedness	AMBER	Equipment fit is suitable; service dates and drills remain incomplete.
Crew & operational preparedness	AMBER	Good coastal experience; extended watchkeeping and failure drills required.
Communications & navigation	GREEN	Appropriate primary and backup systems for the route.
Spares strategy	ORANGE	Inventory does not yet support 18-22 days without technical assistance.

Departure status

☐ READY	☒ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--------------------------------	---	---	--

READINESS MEANING	Conditionally ready means the vessel is suitable for the programme once the defined departure conditions have been completed and tested. It does not mean that the vessel is presently ready to depart or that all possible failure modes have been eliminated.
--------------------------	---

SECTION 04

Intended Cruising Programme

The assessment baseline assumes increasingly remote operation, with the Atlantic passage presenting the most demanding combination of duration, heat, machinery duty and limited external support.

Operating profile

Factor	Assessment baseline
Passage duration	Coastal stages of 1–4 days followed by an Atlantic passage of approximately 18–22 days.
Crew	Owner couple for Europe; two additional competent crew for the Atlantic crossing.
Watchkeeping	Four-person rotating watch system during the Atlantic leg.
Technical support	Good access in Europe; remote support only during the crossing.
Machinery duty	Continuous propulsion, refrigeration, navigation and periodic watermaking.
Weather philosophy	Conservative routing and departure timing; avoidance rather than heavy-weather capability as the primary control.

Crew profile

The owner has approximately 6,000 nautical miles of coastal and near-offshore experience, including overnight passages and one Biscay crossing as crew. The partner has regular watchkeeping experience but limited machinery fault-finding confidence. The two intended Atlantic crew members have sailing and watchkeeping experience but have not yet completed vessel-specific familiarisation.

Environmental and support demands

- Potential heavy-weather exposure during Biscay and the eastern Atlantic.
- Long periods without access to parts, contractors or sheltered harbours.
- High ambient temperature affecting batteries, refrigeration, ventilation and crew fatigue.
- Continuous motion that may mobilise contamination and expose weak securing arrangements.
- Requirement to manage minor machinery, electrical and plumbing failures onboard.

Readiness assessment baseline

OPERATIONAL SCENARIO	The vessel should be capable of maintaining safe propulsion, navigation, communications, steering, bilge control and essential domestic support after a single foreseeable equipment failure, while allowing the crew to diagnose, isolate and manage the problem without immediate external assistance.
-----------------------------	--

SECTION 05

Machinery Readiness

The propulsion and generation installations present a generally strong foundation for the proposed route. Recent baseline maintenance has addressed the age-related exhaust and sterngear items identified during purchase.

Machinery Readiness rating

☒ READY	☐ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--	---	--	---

Main propulsion assessment

Assessment area	Status	Comment
Service history	GREEN	Annual servicing documented; coolant and oil analysis show no adverse trend.
Reliability outlook	GREEN	Twin mechanically independent propulsion trains with stable trial performance.
Accessibility	GREEN	Good access to belts, filters, pumps and major service points.
Maintenance standard	GREEN	Recent hoses, shaft seals and exhaust work evidenced.
Offshore suitability	GREEN	Appropriate for the route subject to routine monitoring.

Both engines completed a six-hour loaded trial after the 2026 remedial work. Temperatures, oil pressure and charging output remained stable.

Power generation assessment

Assessment area	Status	Comment
Reliability	AMBER	Generator is serviceable but remains a high-duty single unit.
Service status	GREEN	Heat exchanger, mounts and cooling hoses serviced in June 2026.
Redundancy	AMBER	Some domestic loads can be supported from inverter and alternators.
Offshore suitability	AMBER	Suitable if load management and inverter fallback are practised.

The generator is not essential to propulsion or primary navigation, but it supports watermaking, battery charging and domestic comfort. Failure would increase workload and require disciplined load management.

Supporting machinery assessment

Assessment area	Status	Comment
Cooling systems	GREEN	Hoses and impellers renewed; spare pumps carried.
Bilge pumping	GREEN	Multiple electric pumps plus high-level alarms and manual pump.
Fresh-water systems	AMBER	Two pumps fitted; watermaker service and spares still required.

Assessment area	Status	Comment
Hydraulic systems	GREEN	Steering and stabiliser systems inspected; emergency isolation documented.
Ancillary systems	AMBER	Refrigeration has limited onboard diagnostic capability.

Supporting systems are generally accessible and appropriately separated. The watermaker and refrigeration systems remain secondary reliability concerns rather than departure barriers.

Machinery Readiness summary

STRENGTHS • Twin propulsion and good machinery access • Recent baseline servicing and completed exhaust/sterngear work • Stable loaded trial results	CONCERNS • Single generator remains a domestic and charging dependency • Watermaker and refrigeration support require better spare coverage • Trend monitoring should be formalised
---	--

Recommended actions

Priority	Action	Timing
1	Carry engine raw-water pump assemblies, belts, sensors and service consumables.	Before departure
2	Complete generator-failure load-management drill.	Before Biscay
3	Record temperatures, pressures and fluid levels during each passage.	Ongoing

ABSOLUTE MARINE CONCLUSION	The machinery systems are considered ready for the intended programme. Continued readiness depends upon disciplined monitoring, sufficient spares and the crew's ability to manage generator loss without compromising essential services.
-----------------------------------	--

SECTION 06

Fuel System Assessment

Fuel capacity and tank isolation are suitable, but the current filtration and contamination-recovery arrangements do not yet provide sufficient resilience for a long ocean passage.

Fuel System Assessment rating

☐ READY	☒ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--------------------------------	--	---	--

Fuel storage assessment

Assessment area	Status	Comment
Capacity for programme	GREEN	4,200 litres provides suitable range with planned reserve.
Tank configuration	GREEN	Four tanks with isolation and transfer capability.
Accessibility	AMBER	Inspection ports are accessible but require preparation.
Inspection evidence	AMBER	Samples are clean; full internal inspection has not been completed.

The vessel can isolate tanks and maintain a conservative reserve. Fuel calculations should use verified consumption from loaded sea trials rather than builder figures.

Filtration and quality management

Assessment area	Status	Comment
Primary filtration	ORANGE	Single service filter per engine; no immediate changeover.
Secondary filtration	GREEN	Engine-mounted filters accessible and recently renewed.
Filter accessibility	GREEN	Filters are reachable underway with safe handholds.
Water detection	AMBER	Bowls are visible; no electronic water alarm.

The principal weakness is not filter quality but the need to stop or interrupt an engine to replace a blocked primary element.

Transfer and contamination resilience

Assessment area	Status	Comment
Transfer reliability	GREEN	Electric transfer pump plus manual bypass.
Fuel balancing	GREEN	Four-tank manifold supports controlled transfer.
Contamination detection	AMBER	Routine sampling procedure not yet established.
Recovery capability	ORANGE	Limited ability to polish or recirculate contaminated fuel.

A contaminated tank can be isolated, but sustained recovery would rely on external cleaning or improvised transfer through portable equipment.

Fuel System Assessment summary

STRENGTHS • Good total capacity and tank separation • Accessible filters and clear manifold arrangement • Recent clean fuel samples	CONCERNS • No primary-filter changeover under load • Tank bottoms have not been fully inspected • No dedicated polishing or recirculation capability
--	---

Recommended actions

Priority	Action	Timing
1	Install duplex or parallel primary-filter changeover for each engine.	Before Atlantic departure
2	Inspect accessible tank bottoms and establish routine low-point sampling.	Before departure
3	Carry at least ten primary and six secondary filter elements plus seals.	Before departure
4	Document contaminated-fuel isolation and recovery procedure.	Before Biscay

ABSOLUTE MARINE CONCLUSION	The fuel system is conditionally ready. Capacity and tank management are strong, but the vessel should not undertake the Atlantic passage until filter changeover and contamination procedures allow the crew to respond without losing both propulsion reliability and situational awareness.
-----------------------------------	--

SECTION 07

Electrical Resilience

The vessel has multiple charging sources and a substantial house bank, but endurance under passage load and genuinely independent emergency charging have not yet been demonstrated.

Electrical Resilience rating

☐ READY	☒ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--------------------------------	--	---	--

Charging system assessment

Assessment area	Status	Comment
Charging redundancy	AMBER	Two engine alternators, generator charger and shore charger; house charging remains concentrated.
Charging capacity	GREEN	Rated capacity is adequate for expected loads.
Charging diversity	AMBER	Solar contribution is modest and weather dependent.
Offshore suitability	AMBER	Suitable after loaded endurance and failure tests.

The main concern is common dependence upon the house-battery distribution and control system rather than a complete absence of charging sources.

Battery and distribution assessment

Assessment area	Status	Comment
House-bank capacity	AMBER	Nominal 1,000 Ah at 24 V; current usable capacity unverified.
Start batteries	GREEN	Independent banks with cross-connect arrangement.
Isolation and protection	GREEN	2026 corrective work completed and labelled.
Critical-system supply	AMBER	Navigation and communications share the house distribution.

Capacity testing should confirm realistic overnight endurance with refrigeration, navigation, communications and autopilot loads.

Emergency electrical capability

Assessment area	Status	Comment
Emergency communications	GREEN	Handheld VHF, satellite device and PLBs have independent batteries.
Emergency navigation	GREEN	Portable charting and GPS devices available.
Alternative charging	ORANGE	No demonstrated method to recharge the house bank after loss of primary control equipment.
Fault recovery	AMBER	Spare fuses and diagrams available; crew practice is limited.

Independent devices support immediate safety, but a prolonged passage requires a credible method of maintaining essential fixed services after a charging-system failure.

Electrical Resilience summary

STRENGTHS • Multiple nominal charging sources • Independent engine-start banks • Corrected cable protection and updated schematics	CONCERNS • House-bank capacity has not been load-tested • Alternative emergency charging remains incomplete • Crew fault-isolation practice is limited
---	---

Recommended actions

Priority	Action	Timing
1	Complete a 24-hour passage-load endurance and recharge test.	Before departure
2	Install or prove an independent emergency charging route to essential loads.	Before Atlantic departure
3	Label essential-load shedding sequence and rehearse it with crew.	Before Biscay
4	Carry critical fuses, relays, contactors and a suitable multimeter.	Before departure

ABSOLUTE MARINE CONCLUSION	The electrical installation is conditionally ready. The physical system is broadly appropriate, but readiness depends upon demonstrating usable capacity, recovery from loss of a principal charging path and crew familiarity with load shedding and fault isolation.
-----------------------------------	--

SECTION 08

Steering & Control Systems

The steering arrangement provides good primary reliability, meaningful autopilot redundancy and a practical emergency method that has been tested alongside the dock.

Steering & Control Systems rating

☒ READY	☐ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--	---	--	---

Primary steering assessment

Assessment area	Status	Comment
Hydraulic condition	GREEN	No leakage; hoses inspected and key flexible sections renewed.
Steering reliability	GREEN	Both helm stations and power-assisted steering operate correctly.
Accessibility	GREEN	Rudder stocks, rams and isolation valves are accessible.
Offshore suitability	GREEN	Appropriate for prolonged operation.

The twin rudders are operated through a common hydraulic architecture, so hose and fluid loss remain important common-mode risks.

Autopilot and redundancy assessment

Assessment area	Status	Comment
Autopilot computers	GREEN	Dual computers with selectable control.
Heading sensors	GREEN	Primary and independent backup sensor available.
Drive arrangements	AMBER	Autopilot drives share hydraulic steering components.
Failure isolation	GREEN	Control switching and manual steering recovery are documented.

Electronic redundancy is good, although both autopilots remain dependent upon the core hydraulic steering system.

Emergency steering capability

Assessment area	Status	Comment
Emergency tiller	GREEN	Accessible and assembled during dockside drill.
Crew familiarity	AMBER	Owner practised; additional Atlantic crew not yet trained.
Practical control	AMBER	Effective at low speed but physically demanding.
Recovery plan	GREEN	Written actions and tools stored with the tiller.

The arrangement is credible as an emergency method but should be practised by the full crossing crew and tested under controlled way before departure.

Steering & Control Systems summary

STRENGTHS • Good access to steering machinery • Dual autopilot computers and backup heading source • Emergency tiller has been assembled and checked	CONCERNS • Common hydraulic components remain a single-point vulnerability • Emergency tiller is physically demanding • Additional crew familiarisation is outstanding
---	---

Recommended actions

Priority	Action	Timing
1	Conduct a controlled emergency-steering trial under way.	Before Atlantic departure
2	Train all crossing crew in isolation valves, fluid top-up and tiller deployment.	Before Canaries
3	Carry hydraulic hose repair materials and correct fluid quantity.	Before departure

ABSOLUTE MARINE CONCLUSION	The steering and control systems are considered ready, subject to completion of a full-crew practical drill. The primary arrangement is reliable and accessible, and the emergency method is credible rather than merely theoretical.
-----------------------------------	---

SECTION 09

Safety & Emergency Preparedness

The vessel carries an appropriate equipment inventory, but several service dates, stowage decisions and practical drills remain incomplete.

Safety & Emergency Preparedness rating

☐ READY	☒ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--------------------------------	--	---	--

Emergency equipment assessment

Assessment area	Status	Comment
Liferaft and survival equipment	AMBER	Liferaft service booked; grab-bag inventory incomplete.
Lifejackets and personal equipment	GREEN	Offshore lifejackets, lights, AIS beacons and tethers provided.
EPIRB / PLBs	GREEN	Current batteries and registrations verified.
Abandon-ship preparation	AMBER	Roles and deployment sequence not yet rehearsed.

Equipment quality is generally appropriate. Readiness now depends more upon service completion, stowage and crew use than further purchasing.

Fire and flooding preparedness

Assessment area	Status	Comment
Fixed suppression	GREEN	Engine-room system serviced June 2026.
Portable extinguishers	GREEN	Current service dates and suitable distribution.
Detection systems	GREEN	Smoke, heat and machinery-space alarms tested.
Flooding response	AMBER	Collision mat and softwood plugs carried; drill incomplete.

The crew should know which ventilation, fuel, electrical and machinery controls must be isolated during a fire or flooding event.

Medical and crew response

Assessment area	Status	Comment
Medical kit	AMBER	Offshore kit assembled; prescription review pending.
Medical competence	AMBER	One crew member has current offshore first aid.
Emergency communications	GREEN	VHF DSC, satellite voice/data and independent devices.
Practical drills	ORANGE	Man-overboard, fire, flooding and abandon-ship drills outstanding.

The principal gap is procedural. Equipment cannot substitute for practised allocation of roles and rapid access under pressure.

Safety & Emergency Preparedness summary

STRENGTHS • Appropriate offshore safety-equipment inventory • Current EPIRB, PLBs and personal AIS devices • Serviced fire detection and suppression	CONCERNS • Liferaft service and grab-bag completion pending • Only one crew member currently holds recent offshore medical training • Practical emergency drills remain outstanding
---	--

Recommended actions

Priority	Action	Timing
1	Complete liferaft service, grab bags and expiry register.	Before departure
2	Conduct fire, flooding, man-overboard and abandon-ship drills.	Before Biscay
3	Complete crew medical review and remote-support plan.	Before Canaries
4	Issue a vessel-specific safety briefing card at each berth.	Before departure

ABSOLUTE MARINE CONCLUSION	Safety and emergency preparedness is conditionally ready. The equipment fit is suitable, but offshore departure should wait until dated items are current and the full crew has demonstrated the ability to locate, deploy and use the equipment under realistic conditions.
-----------------------------------	--

SECTION 10

Crew & Operational Preparedness

The owner has a sound operating philosophy and good coastal experience, but the intended Atlantic crew has not yet demonstrated vessel-specific watchkeeping, fault response or emergency coordination.

Crew & Operational Preparedness rating

☐ READY	☒ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--------------------------------	--	---	--

Vessel familiarity

Assessment area	Status	Comment
Owner systems knowledge	GREEN	Good understanding of machinery, valves and electrical isolation.
Partner familiarity	AMBER	Confident in normal operation; limited machinery diagnosis.
Additional crew familiarity	ORANGE	Not yet completed full systems or emergency briefing.
System documentation	GREEN	Updated diagrams and digital manuals available.

The owner should avoid becoming the sole person capable of handling every technical or emergency decision.

Passage planning and procedures

Assessment area	Status	Comment
Route and weather planning	GREEN	Conservative staged plan with suitable diversion options.
Fuel and range planning	GREEN	Loaded consumption figures and 25% reserve applied.
Watchkeeping plan	AMBER	Proposed schedule exists but has not been tested.
Departure procedures	GREEN	Written machinery, deck and navigation checks in use.

A multi-day shakedown should confirm fatigue, meal preparation, handover quality and realistic maintenance workload.

Decision making and resilience

Assessment area	Status	Comment
Go / no-go philosophy	GREEN	Owner demonstrates willingness to delay.
Troubleshooting ability	AMBER	Owner competent; wider crew capability limited.
Failure operation	AMBER	Procedures written but not all practised.
Overall confidence	AMBER	Credible after shakedown and drills.

The operational plan should distribute knowledge, particularly for fire response, steering isolation, bilge control and communications.

Crew & Operational Preparedness summary

STRENGTHS • Conservative owner decision making • Good owner familiarity and updated documentation • Route planning includes diversion and reserve margins	CONCERNS • Technical knowledge is concentrated in one person • Watchkeeping plan remains untested • Additional crew require vessel-specific familiarisation
--	--

Recommended actions

Priority	Action	Timing
1	Complete a three-night offshore shakedown with the intended watch system.	Before Atlantic departure
2	Allocate technical and emergency roles to all crew.	Before Biscay
3	Practise engine-room checks, log keeping and abnormal-event handovers.	During shakedown
4	Set fatigue and weather thresholds requiring delay or diversion.	Before departure

ABSOLUTE MARINE CONCLUSION	Crew and operational preparedness is conditionally ready. The owner’s judgement and knowledge are strengths, but the programme should not depend upon one person remaining continuously available and unimpaired. A multi-day shakedown and structured crew familiarisation are essential departure conditions.
-----------------------------------	---

SECTION 11

Communications & Navigation

The vessel carries suitable primary and independent backup navigation and communications equipment for the route, supported by current charts and a conservative passage-planning process.

Communications & Navigation rating

☒ READY	☐ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--	---	--	---

Navigation equipment assessment

Assessment area	Status	Comment
Primary navigation	GREEN	Dual networked multifunction displays with current charts.
Radar and AIS	GREEN	Two radar scanners and Class B+ AIS tested.
Position redundancy	GREEN	Independent GNSS receivers and portable devices.
Offshore suitability	GREEN	Appropriate for expected route and watchkeeping.

The primary network remains a common dependency, but independent portable navigation preserves position awareness after network or display failure.

Communications assessment

Assessment area	Status	Comment
VHF communications	GREEN	Fixed DSC sets at two stations plus handhelds.
Long-range communications	GREEN	Satellite voice/data and independent text device.
Distress alerting	GREEN	EPIRB, PLBs, DSC and personal AIS devices.
Communication redundancy	GREEN	Multiple independent power sources and technologies.

Registration details, emergency contacts and airtime plans should be checked immediately before departure.

Operational management

Assessment area	Status	Comment
Charts and publications	GREEN	Digital charts current; relevant paper overview charts carried.
Weather information	GREEN	Multiple forecast and routing sources planned.
Crew familiarity	AMBER	Additional crew require radar and distress-procedure briefing.
Failure recovery	GREEN	Portable charting and written positions support recovery.

The full crew should know how to transmit a DSC distress, locate the vessel position and use the independent satellite device.

Communications & Navigation summary

STRENGTHS • Strong primary navigation and radar capability • Independent portable navigation and communications • Multiple distress-alerting methods	CONCERNS • Primary displays share network and house-power dependencies • Additional crew require practical briefing • Airtime and registration checks must remain current
---	--

Recommended actions

Priority	Action	Timing
1	Brief all crew on DSC, satellite and independent navigation devices.	Before departure
2	Download and print emergency contact and communication procedures.	Before departure
3	Test independent devices during the shakedown passage.	Before Atlantic departure

ABSOLUTE MARINE CONCLUSION	Communications and navigation arrangements are considered ready. The system mix provides credible redundancy, and the remaining actions relate principally to crew familiarity and final verification rather than equipment deficiency.
-----------------------------------	---

SECTION 12

Spares Strategy

The current spares inventory supports routine coastal servicing but does not yet provide enough depth, organisation or system coverage for an 18–22 day passage without immediate technical support.

Spares Strategy rating

☐ READY	☐ CONDITIONALLY READY	☒ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--------------------------------	--	---	--

Critical machinery spares

Assessment area	Status	Comment
Engine service spares	AMBER	Filters, belts and impellers carried; sensor and pump coverage incomplete.
Generator spares	AMBER	Routine consumables carried; starter and raw-water components incomplete.
Cooling-system spares	AMBER	Hose and clamps available; formed hoses and caps limited.
Fuel-system spares	ORANGE	Insufficient filter quantity and no changeover seals kit.

The inventory is strongest in routine consumables and weakest in components that would restore operation after a foreseeable failure.

Electrical and control spares

Assessment area	Status	Comment
Fuses and protection	GREEN	Broad fuse and breaker coverage.
Relays and contactors	AMBER	Some common ratings carried; critical proprietary items absent.
Repair materials	GREEN	Cable, terminals, heat-shrink and crimping tools available.
Control components	ORANGE	Limited spare sensors, switches and pump controllers.

A small number of carefully selected proprietary parts may provide more value than a large quantity of generic consumables.

Tools and organisation

Assessment area	Status	Comment
General tools	GREEN	Good mechanical and electrical hand-tool coverage.
Specialist tools	AMBER	Pullers, pressure tools and hose equipment limited.
Diagnostic equipment	AMBER	Multimeter and infrared thermometer available; no pressure gauges.
Inventory management	ORANGE	Parts stored in several areas without a reliable index.

In an emergency, knowing whether a part is onboard and where it is stowed is as important as carrying it.

Spares Strategy summary

STRENGTHS • Good general tool kit and repair materials • Routine service consumables already onboard • Owner has practical maintenance ability	CONCERNS • Critical proprietary spares remain incomplete • Fuel-filter quantity is insufficient • Inventory is not indexed by system and stowage location
---	--

Recommended actions

Priority	Action	Timing
1	Create a critical-spares list from single-point failure analysis.	Before departure
2	Increase fuel, cooling, pump and electrical-control spares.	Before Atlantic departure
3	Label containers and create a searchable stowage index.	Before Biscay
4	Conduct two simulated repairs using only onboard tools and parts.	During shakedown

ABSOLUTE MARINE CONCLUSION	The spares strategy currently requires significant preparation. This is the only area rated below conditionally ready because the gap directly affects self-sufficiency during the longest passage. The weakness is readily correctable through disciplined selection, organisation and practical testing.
-----------------------------------	--

SECTION 13

Detailed Readiness Assessment

This section integrates the individual system findings into one engineering judgement about the vessel, the people operating it and the proposed voyage.

Assessment area	Status	Integrated view
Technical platform	GREEN	Strong underlying machinery, steering and navigation arrangements.
Failure recovery	AMBER	Fuel, electrical and spares actions remain necessary.
Crew capability	AMBER	Owner strength is offset by concentration of knowledge.
Emergency preparedness	AMBER	Equipment suitable; practical drills incomplete.
Self-sufficiency	ORANGE	Current spares and repair planning do not match the Atlantic leg.
Programme suitability	AMBER	Appropriate once departure conditions are completed and tested.

Principal strengths

- ✓ Twin propulsion and good machinery access.
- ✓ Recent remediation of survey-critical exhaust, sterngear and electrical items.
- ✓ Robust navigation, communication and steering arrangements.
- ✓ Conservative route planning and willingness to delay.

Principal vulnerabilities

- ⚠ Fuel contamination recovery is not yet strong enough for the programme.
- ⚠ Electrical endurance and alternative charging remain unproven.
- ⚠ Technical knowledge is concentrated in the owner.
- ⚠ Spares depth and organisation do not yet match the period away from support.

Operational risk

Measure	Current assessment	After Priority 1 actions
Overall technical risk	Moderate	Low to moderate
Overall operational risk	Moderate	Low to moderate
Self-sufficiency	Limited to good	Good
Departure confidence	Conditional	Appropriate for planned route

Suitability for intended programme

The vessel's size, capacity, machinery arrangement and navigation fit are suitable for the proposed route. The longest Atlantic leg, however, changes the threshold from equipment serviceability to recoverability. A blocked filter, reduced house-bank capacity, failed pump controller or fatigued key crew member must be manageable without immediate professional assistance.

Overall engineering judgement

ENGINEERING JUDGEMENT	M/Y Ardent is a credible offshore vessel with a sound technical base. It is not yet ready to depart because several high-consequence preparations remain uncompleted or untested. Completion of the fuel-filtration upgrade, electrical endurance and recovery testing, safety drills, crew shakedown and critical-spares programme should move the vessel from conditionally ready to ready for the intended route.
------------------------------	--

SECTION 14

Recommendations

Recommendations are divided by their effect on departure readiness rather than by convenience or visibility.

Priority 1 — before offshore departure

Recommendation	Reason	Completion evidence
Install primary fuel-filter changeover and inspect tank bottoms.	Reduces likelihood and consequence of fuel-related propulsion interruption.	Installation test, samples and written procedure
Complete 24-hour electrical endurance and recharge test.	Confirms realistic house-bank capacity and charging performance.	Recorded load, voltage and recharge data
Establish independent emergency charging / essential-load route.	Preserves critical services after a principal charging failure.	Demonstrated recovery test
Service liferaft and complete all emergency drills.	Converts equipment inventory into practical preparedness.	Certificates and signed drill record
Build critical-spares inventory and stowage index.	Improves self-sufficiency and reduces fault-recovery delay.	Inventory, photographs and simulated repair
Complete three-night offshore shakedown with intended crew.	Tests watchkeeping, fatigue, meals, procedures and system loading.	Debrief and closed action list

Priority 2 — before the Atlantic leg

Recommendation	Benefit	Timing
Conduct emergency steering trial under way.	Confirms practical control and crew capability.	Before Canary Islands
Service watermaker and carry membrane/pump consumables.	Improves domestic resilience and reduces water dependence.	Before Portugal
Expand proprietary electrical and pump-controller spares.	Improves recovery from common control failures.	Before Canaries
Complete second crew member offshore medical training.	Reduces single-person medical dependency.	Before Atlantic departure
Review tropical ventilation and refrigeration performance.	Reduces overheating and food-storage risk.	During southern passage

Priority 3 — longer-term improvements

Recommendation	Long-term benefit
Add modest solar capacity and segregated emergency charging.	Reduces generator dependence and improves silent endurance.
Install fuel-water detection or routine sampling points.	Improves early contamination detection.
Develop annual failure-drill programme.	Maintains crew confidence as equipment and crew change.

Recommendation	Long-term benefit
Add machinery trend dashboard.	Makes gradual temperature, pressure and consumption changes visible.

Readiness outlook

ABSOLUTE MARINE RECOMMENDATION	The owner should treat the Priority 1 actions as a single departure gate. Completing isolated items without the endurance test, crew shakedown and simulated recovery would not provide the same confidence. Once the actions are complete, the readiness rating should be reviewed against the evidence rather than automatically upgraded.
---------------------------------------	--

SECTION 15

Conclusion

The final opinion considers whether the vessel, its systems and intended crew collectively support the proposed cruising programme.

Overall assessment

☐ READY	☒ CONDITIONALLY READY	☐ SIGNIFICANT PREPARATION REQUIRED	☐ NOT CURRENTLY READY
--------------------------------	--	---	--

Summary of findings

- The vessel has a strong underlying machinery, steering and navigation platform.
- The fuel and electrical systems require defined resilience improvements and practical testing.
- Safety equipment is appropriate, but service completion and drills remain essential.
- The spares strategy is presently below the standard required for the Atlantic leg.
- The owner's conservative judgement is positive, but knowledge must be distributed across the crew.

Final engineering opinion

FINAL OPINION	In Absolute Marine's opinion, the fictional M/Y Ardent is conditionally ready for the planned voyage from the United Kingdom to the Caribbean. The vessel is suitable in principle and the identified deficiencies are achievable preparations rather than fundamental design barriers. Departure should follow completion and demonstration of the Priority 1 fuel, electrical, safety, crew and spares actions. A short readiness review after the shakedown passage would provide the most reliable basis for confirming the final departure status.
----------------------	---

Closing statement

Successful offshore cruising is rarely defined by the absence of technical problems. It is defined by whether predictable problems have been anticipated, whether the crew can recognise them early and whether the vessel can remain safe while the problem is managed. Preparedness does not remove uncertainty; it allows uncertainty to be handled with confidence.

SECTION 16

Disclaimer

This wording forms part of the example and illustrates the limits of a real Offshore Readiness Review.

Scope

This is a fictional demonstration report. The vessel, client, equipment, records, findings and voyage are invented and must not be relied upon for any real operation.

Nature of assessment

An Offshore Readiness Review is an advisory engineering assessment against a stated cruising programme. It is not a condition survey, statutory inspection, class inspection, insurance survey, sea trial or guarantee of seaworthiness.

Information and limitations

A real review depends upon the completeness and accuracy of information supplied and any agreed inspection. Equipment condition and crew capability may change after the assessment.

Recommendations

Recommendations support prioritisation and risk reduction. They do not guarantee future reliability or confirm that every possible defect or failure mode has been identified.

Responsibility

The owner remains responsible for the safe operation of the vessel, crew competence, maintenance, passage planning and the decision whether to undertake any voyage.

Copyright

Copyright © Absolute Marine. This fictional example may be published by Absolute Marine but may not be represented as an assessment of any real vessel, owner or voyage.